

Site 8 – Tilton Property



Buttressed Roots,
Multiple Trunks

Site 8 – Tilton Property



Moss is not a
reliable indicator

Site 8 – Tilton Property



Stain on Concrete Foundation
681.4

Site 8 – Tilton Property




Site 8 – Tilton Property



Swamp White
Oak Leaf

Site 9 Railroad Swing Bridge



Site 9 Railroad Swing Bridge



Site 9 Railroad Swing Bridge



Undercut Root Mass
681.6

Site 9 Railroad Swing Bridge



Horizontal
Roots 681.9

Site 9 Railroad Swing Bridge



Stain 681.9

Site 9 Railroad Swing Bridge



Tree bark
Scour 683.2

Site 9 Railroad Swing Bridge

